

Flight Design GmbH

Sielminger Str. 65 D-70771 L.-Echterdingen Tel +49 (0)711 90287-0 Fax +49 (0)711 90287-99

E-Mail: info@flightdesign.com

SN-LTUL-CT__-04; SN-LTUL-CT2k-05; SN-LTUL-CTSW-03 Revision 0

Date of Initial Publication: **15-Oct-2008**Publication Date of this Revision: **15-Oct-2008**

Service NOTIFICATION

Upper rudder hinge

SN-LTUL-CT__-04; SN-LTUL-CT2k-05; SN-LTUL-CTSW-03

1 Planning Information

1.1 Affected Aircraft

Type: CT

Model: CT, CT2k, CTSW
Serial Number: All serial numbers

Applicable Countries: All Countries where LTF-UL standards are in effect

1.2 Concurrent Documents

None

1.3 Reason

Re- issue of existing document in order to implement it to the new Service document numbering system

1.4 Subject

All information see paragraph 3

1.5 Compliance

All information see paragraph 3

1.6 Personnel Qualifications

All information see paragraph 3

1.7 Approval

All information see paragraph 3

1.8 Weight and Center of Gravity

All information see paragraph 3



Flight Design GmbH

Sielminger Str. 65 D-70771 L.-Echterdingen Tel +49 (0)711 90287-0 Fax +49 (0)711 90287-99

E-Mail: info@flightdesign.com

SN-LTUL-CT__-04; SN-LTUL-CT2k-05; SN-LTUL-CTSW-03 Revision 0

Date of Initial Publication: **15-Oct-2008**Publication Date of this Revision: **15-Oct-2008**

1.9 References

All information see paragraph 3

1.10 Superseded Documents

Technical Advice No. 5

Safety Directive No. 5

1.11 Contact Details

For further information or to report any Safety of Flight or Service Difficulty issues contact your Distributor responsible for your country.

Specific contact in USA:

Flight Design USA

P.O. Box 325 South Woodstock, CT 06267 Tel: 860 963 7272 / Fax: 860 963 7152

Web: www.flightdesignUSA.com

E-Mail: airworthiness@flightdesignUSA.com

For all other countries and in cases where the local distributor is not known or available contact Flight Design GmbH directly.

2 Resources

2.1 Materials

All information see paragraph 3

2.2 Manpower

All information see paragraph 3

2.3 <u>Cost</u>

All information see paragraph 3

3 Instructions

The following is the 1:1 copy of the existing document following the old numbering system.



Flight Design GmbH

Sielminger Str. 65 D-70771 L.-Echterdingen Tel +49 (0)711 90287-0 Fax +49 (0)711 90287-99

E-Mail: info@flightdesign.com

SN-LTUL-CT__-04; SN-LTUL-CT2k-05; SN-LTUL-CTSW-03 Revision 0

Date of Initial Publication: **15-Oct-2008**Publication Date of this Revision: **15-Oct-2008**

TECHNICAL ADVISE No. 5

Issue Date: 01.07.2003

Subject:

All CT's and CT2K's. Upper hinge of the rudder.

Case:

At the plane serial no. 01-06-02-12 the bush, part no. KA3020511, got loose at the rudder nose rib, part no. KA3020500ASSY at 80 hours.


<u>Analysis:</u>

It's very unlikely but as it seems gluing between the threaded bush and the rib was destroyed and the bush was screwed into the rib.

Advise:

- 1. Check that the bush is fixed, but not loosened.
- 2. Check that the position of the bush and the rib is correct (refer to Fig.1). The position of the bush on Fig. 2 & 3 is not correct and shown in purpose.
- 3. If items 2& 3 are found let repair rudder at an authorized repair station.

Fig. 1






Flight Design GmbH
Sielminger Str. 65
D-70771 L.-Echterdingen
Tel +49 (0)711 90287-0
Fax +49 (0)711 90287-99

E-Mail: info@flightdesign.com

SN-LTUL-CT__-04; SN-LTUL-CT2k-05; **SN-LTUL-CTSW-03 Revision 0**

Date of Initial Publication: 15-Oct-2008 Publication Date of this Revision: 15-Oct-2008

Fig. 2





Flight Design GmbH


Sielminger Str. 65 D-70771 L.-Echterdingen Tel +49 (0)711 90287-0 Fax +49 (0)711 90287-99

E-Mail: info@flightdesign.com

SN-LTUL-CT__-04; SN-LTUL-CT2k-05; SN-LTUL-CTSW-03 Revision 0

Date of Initial Publication: **15-Oct-2008**Publication Date of this Revision: **15-Oct-2008**

Fig. 3



4 Appendix

4.1 Changes to Previous Revision

No content changes - re-issue of existing document to new numbering system

4.2 <u>Feedback Template Flight Design</u>

All information see paragraph 3