^	LIFTAIRO
FLIGHT	DESIGN

Am Flugplatz 3, D-99820 Hörselberg Hainich, Airfield Eisenach-Kindel

Web: www.flightdesign.com; Phone: +49 36920 7530-10

E-mail: airworthiness@flightdesign.com

Service Bulletin

SB-ASTM-F2-02, Revision 02

Date of Initial Publication: 09-Sep-2024 Publication Date of this Revision: 26-Sep-2024

Service Bulletin

Exchange of Fuel selector valve SB-ASTM -F2-02

Repeating Symbols:

Please pay attention to the following symbols throughout this document emphasizing particular information.

Identifies an instruction, which if not followed may cause serious injury or even death. **▲** Warning:

■ Caution: Denotes an instruction which if not followed, may severely damage the aircraft or could lead to

suspension of warranty.

Information useful for better handling. Note:

Planning Information

1.1 **Affected Aircraft**

F2 Type:

Model: F2-LSA

Serial Number: T-20-12-01, T-20-12-02, T-21-01-02, T-21-01-03, T-21-02-01, T-23-01-01

23-02-01, T-23-03-01, T-23-04-01, T-23-05-01, T-23-06-01, T-23-06-02

Applicable Countries: Not limited

1.2 **Concurrent Documents**

- none -

1.3

The fuel selector valve on certain aircraft of the list in section 1.1 exhibited problems one or both of the problems described below:

- 1. The return fuel flow is not evenly divided into the left and right fuel tank when both fuel tanks are selected. This may lead to overfilling of one fuel tanks with the result that fuel is pumped over board.
- 2. Fuel supply is unreliable when either left or right fuel tank is selected. That may lead into fuel starvation and subsequent engine failure.

1.4 Subject

The document introduce the dismantling of the Fuel selector valve and the installation of the new one including all necessary additional parts.

T-

^		LIFTAIR
7	FLIGHT	DESIGN

Am Flugplatz 3, D-99820 Hörselberg Hainich, Airfield Eisenach-Kindel

Web: www.flightdesign.com; Phone: +49 36920 7530-10
E-mail: airworthiness@flightdesign.com

Service Bulletin

SB-ASTM-F2-02, Revision 02

Date of Initial Publication: **09-Sep-2024**Publication Date of this Revision: **26-Sep-2024**

1.5 Compliance

Compliance must be shown prior to next flight.

Safety alert SA-ASTM-F2-02 is superseded in case this service bulletin is embodied. This includes:

- Replacement of the fuel selector as per section 2 and 3 of this service bulletin.
- Issue of new revision Pilot's Operating Handbook F2 AT 0430 0001 03.

▲Warning: Non-compliance with these instructions could result in further damages,

personal injuries or death.

1.6 Approval

This SB is approved by the aircraft manufacturer i.a.w. ASTM F3198 for conduct on aircraft as defined in 1.1. Subsequent to complete and correct conduct of this SB the aircraft will still meet the requirements of the applicable ASTM design and performance specification.

1.7 Type of Maintenance

Heavy

1.8 Personnel Qualifications

For US LSA aircraft: Repairman, Light Sport Aircraft-Maintenance (RLSA-M) – holds a repairman certificate (light sport aircraft) with a maintenance rating, A&P, IA or an FAA repair station.

1.9 Release to Service

Conduct of this SB must be logged in the aircraft log book with date and signature of the responsible Person according to national regulations.

1.10 Weight and Balance

The effect to empty aircraft weight and cg is significantly below 0.45 kg (1 lb). Therefore, in compliance with FAA publication AC 43.13-1B reweighing of the aircraft is not required due to this measure alone.

▲ Warning:

When this exemption has been used already for earlier maintenance events on the aircraft, or when other maintenance events are conducted in parallel and the weight changes of the individual events add up to more than 0.45 kg (1 lb), re-weighing of the aircraft is required for the sum of the effects.

1.11 References

Drawings:

Information provided in this SB has been created to ensure a full vision of required changes which differ from the Type design shown in the drawing DT 2800 0000 Fuel system fuselage 07.Feb.24.

1.12 Superseded Documents

Safety alert SA-ASTM-F2-02 is superseded in case this service bulletin is embodied

^	LIFTAIRO
FLIGHT	DESIGN

Am Flugplatz 3, D-99820 Hörselberg Hainich, Airfield Eisenach-Kindel

Web: www.flightdesign.com; Phone: +49 36920 7530-10 E-mail: airworthiness@flightdesign.com Service Bulletin

SB-ASTM-F2-02, Revision 02

Date of Initial Publication: **09-Sep-2024**Publication Date of this Revision: **26-Sep-2024**

1.13 Contact Details

For further information on conduct of this SA, or to report any issues, contact your distributor responsible for your country. Your distributor can be located via the Flight Design general aviation website: www.flightdesign.com under "Dealer Location". In cases where the local distributor is not known or available contact Flight Design general aviation GmbH directly:

Flight Design general aviation GmbH

Am Flugplatz 3

99820 Hörselberg Hainich

Germany

web www.flightdesign.com

e-mail <u>airworthiness@flightdesign.com</u>

tel +49 36920 7530 10

Specific contact in USA:

Airtime Aviation inc.

8505 S. Elwood Ave. B135

Tulsa, OK. 74132

United States of America

web www.flyct.com
e-mail tomjr@flyct.com
tel +1 918 299 2442

1.14 Disclaimer

This Service Bulletin has been generated with utmost care. Nevertheless errors and misunderstandings can never be fully excluded. In case of any doubts the applicant of this Service Bulletin is requested to contact Flight Design immediately to clarify the issue.

2 Resources

2.1 Pilot Operating Handbook

The pilot operating handbook must be updated to revision 3, doc.-no. AT 0430 0001_03.

^	LIFTAIR
FLIGHT	DESIGN

Am Flugplatz 3, D-99820 Hörselberg Hainich, Airfield Eisenach-Kindel

Web: <u>www.flightdesign.com;</u> Phone: +49 36920 7530-10 E-mail: <u>airworthiness@flightdesign.com</u>

Service Bulletin

SB-ASTM-F2-02, Revision 02

Date of Initial Publication: **09-Sep-2024**Publication Date of this Revision: **26-Sep-2024**

2.2 Parts

Specification of parts to produce required changes is shown in table 1.

Table 1

Pos	View	Description	Q-ty, pcs
1	A GHT OFF	FS2020 Duplex Fuel Selector	1
2	7905G Andair Check Valve CK375-MH-14-BRO IR23-10-02-282	Check Valve CK375-MH-14-BRP	1
3		T flared tube AN6 Male-female	1



Am Flugplatz 3, D-99820 Hörselberg Hainich, Airfield Eisenach-Kindel

Web: <u>www.flightdesign.com</u>; Phone: +49 36920 7530-10 E-mail: <u>airworthiness@flightdesign.com</u>

Service Bulletin

SB-ASTM-F2-02, Revision 02



^		LIFTAIR
*	FLIGHT	DESIGN

Am Flugplatz 3, D-99820 Hörselberg Hainich, Airfield Eisenach-Kindel

Web: www.flightdesign.com; Phone: +49 36920 7530-10 E-mail: airworthiness@flightdesign.com

Service Bulletin

SB-ASTM-F2-02, Revision 02

7	7018W Phenix 90° Swivel Coupler ANG-ANG fitting C690-2 IR23-07-12-120	PHENIX 90 deg Swivel Coupler AN6-AN6 Fitting C690-2	2
8	72630 AN FITTINGS AN821-6D ELBOW IR23-07-12-P	AN Fitting Elbow AN821-6D	1
9	7259B WWW AN FITTINGS ANSIS-6D UNION UNION UNION IIIII M IR24-05-05-011	AN Fitting AN815-6D UNION	1
10		Swage fitting 10mm Nut 9/16-18 UNF	1

^	LIFTAIR
FLIGHT	DESIGN

Am Flugplatz 3, D-99820 Hörselberg Hainich, Airfield Eisenach-Kindel

Web: www.flightdesign.com; Phone: +49 36920 7530-10 E-mail: airworthiness@flightdesign.com

Service Bulletin

SB-ASTM-F2-02, Revision 02

11		Spacer for installation Fuel bracket	1
12	RIGHT OF KNOWN AND SWILL AND	New design Fuel Selector Handle Cover	1
13		Connection Flange ECA1#2	1



Am Flugplatz 3, D-99820 Hörselberg Hainich, Airfield Eisenach-Kindel

Web: www.flightdesign.com; Phone: +49 36920 7530-10 E-mail: airworthiness@flightdesign.com

Service Bulletin

SB-ASTM-F2-02, Revision 02






Am Flugplatz 3, D-99820 Hörselberg Hainich, Airfield Eisenach-Kindel

Web: www.flightdesign.com; Phone: +49 36920 7530-10 E-mail: airworthiness@flightdesign.com

Service Bulletin

SB-ASTM-F2-02, Revision 02



^		LIFT	MR O
F	LIGHT	DESIG	N

Am Flugplatz 3, D-99820 Hörselberg Hainich, Airfield Eisenach-Kindel

Web: www.flightdesign.com; Phone: +49 36920 7530-10 E-mail: airworthiness@flightdesign.com Service Bulletin

SB-ASTM-F2-02, Revision 02

24	6167 Bolt DIN 912 M3x8-8.8 IR23-10-54-005	Bolt M3x8-8.8 DIN 912	1
25	Altereft Spruce AN526-832R8 Schemany Co. 30 LOC: 211G PO: 1088-89 QTY: 100 LOT: 105081/66757-02	Screw AN526-832R8	1
26	Socket isol. 5mm 1,5-2,5sqm	For restore Yellow wire of OVP module step See step 3.7	1
27	6503 Washer DIN 125 5.3mm 140HV (A2K) O Expi Pouz n/a 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Washer DIN 125 5.3mm 140HV A2K	16

^		LIFTAIR
7	FLIGHT	DESIGN

Am Flugplatz 3, D-99820 Hörselberg Hainich, Airfield Eisenach-Kindel

Web: www.flightdesign.com; Phone: +49 36920 7530-10 E-mail: airworthiness@flightdesign.com

Service Bulletin

SB-ASTM-F2-02, Revision 02

Date of Initial Publication: 09-Sep-2024 Publication Date of this Revision: 26-Sep-2024

28	6563 Washer DIN 9021-5.3mm VZ	Washer DIN 9021-5,3mm	4
29	6204 Bolt DIN 7991 M4x16 IR23-10-54-002	Screw M4x16 DIN 7991	1

2.3 **Materials**

- 1. Sealing material EZ TURN (FUELLUBE) 5 OZ TUBE
- 2. Loctite 648
- 3. Bonding liquid middle strength (Green)
- 4. Odurless end Dip

2.4 **Tools**

1. Tools for metall parts adjustment (See Pic. 2.1)



3- Metall file, 4-Pliers,5- Safety glasses, 6-Cutting wheel for metal,7-Cutting machine Pic.2.1 Tools for metall parts adjustment

^	LIFTAIRO
FLIGHT	DESIGN

Am Flugplatz 3, D-99820 Hörselberg Hainich, Airfield Eisenach-Kindel

Web: www.flightdesign.com; Phone: +49 36920 7530-10 E-mail: airworthiness@flightdesign.com

Service Bulletin

SB-ASTM-F2-02, Revision 02


Date of Initial Publication: **09-Sep-2024**Publication Date of this Revision: **26-Sep-2024**

2. Drill tool with with a set of drills and taps (M2,M3 and 8-32) for working with metal (See pic.2.2)



Pic. 2.2 Drill tool

3. Vise with aluminum inserts (See pic.2.3)



Pic. 2.3 Vise with aluminum inserts



Am Flugplatz 3, D-99820 Hörselberg Hainich, Airfield Eisenach-Kindel

Web: www.flightdesign.com; Phone: +49 36920 7530-10 E-mail: airworthiness@flightdesign.com **Service Bulletin**

SB-ASTM-F2-02, Revision 02

Date of Initial Publication: **09-Sep-2024**Publication Date of this Revision: **26-Sep-2024**

4. Crimping tool 0,5-6,0 mm² or equivalent (See pic.2.4)



Pic 2.4 Crimping tool

2.5 Special Tools

- none -

2.6 Manpower

The described task can be performed within approximately 8 hours (working time).

2.7 Cost

Spare parts will be provided by Flight Design free of charge.

3 Instructions

3.1 General

Actions begin with the dismantling of all the necessary parts to provide access to the area for performing the main work actions. Second part is about replacing the selector and installing the new one with all needed additional parts. The last part describes the assembly of all the parts dismantled in the first part.

3.2 General Procedures

AC 43.13-1B: Acceptable Methods, Techniques, and Practices - Aircraft Inspection and Repair

^		LIFTAIR
**	FLIGHT	DESIGN

Am Flugplatz 3, D-99820 Hörselberg Hainich, Airfield Eisenach-Kindel

Web: www.flightdesign.com; Phone: +49 36920 7530-10 E-mail: airworthiness@flightdesign.com

Service Bulletin

SB-ASTM-F2-02, Revision 02

Date of Initial Publication: **09-Sep-2024**Publication Date of this Revision: **26-Sep-2024**

3.3 Detailed Procedure

Part 1 Dismantling parts to gain access to the main work area

• **Note:** All disassembled parts must be retained for use. This does not apply to parts that were damaged during disassembly or parts that needed to be changed at every assembly as like as Self-locking nuts.


Step 1 Disassembling of Armrest

1.1 Unscrew bolts AN526-832R6 -6pcs and Knob ball - 1pcs (See Pic.3.1)



Pic.3.1 Armrest installation Right side. For left side is mirrored

- 1.2 Disassemble the throttle grip (See Pic.3.2)
- Note: Lock nut M3 DIN 985 A2 should be changed with a new one while assembling throttle grip in part 3.



Pic. 3.2 Scheme of throttle grip installation



Am Flugplatz 3, D-99820 Hörselberg Hainich, Airfield Eisenach-Kindel

Web: www.flightdesign.com; Phone: +49 36920 7530-10

E-mail: airworthiness@flightdesign.com

Service Bulletin

SB-ASTM-F2-02, Revision 02

Date of Initial Publication: 09-Sep-2024 Publication Date of this Revision: 26-Sep-2024

1.3 Disconnect the Jack connectors and remove the armrest (See Pic.3.3)



Pic. 3.3 Jack connectors

Step 2 Disassembling of Lower section panel (See Pic.3.4)

- 2.1 Unscrew 4 pcs screws AN526-832R8 with polyamide washers.
- 2.2 Unsrew 1 pcs screw M3x15 of Fuel sector handle.
- 2.3 Dissassemble Lower panel and disconnect all connectors.
- 2.4 Dissassemble Heat Grip. Unscrew Knurled nut.
- 2.5 Uncrew 4 pcs screws M5x16 with Self-locking nuts M5 DIN 985 of fuel selector cover.
- 2.6 Dissconnect electric connections.
- Note: Lock nuts M5 DIN 985 should be changed with a new one while assembling in part 3.
- Screws M5x16 should be changed with a Screws M5x20 (See table 1 item 22) while assembling in part 3. Note:



Pic 3.4 Scheme of Installation Lower section panel



Am Flugplatz 3, D-99820 Hörselberg Hainich, Airfield Eisenach-Kindel

Web: www.flightdesign.com; Phone: +49 36920 7530-10 E-mail: airworthiness@flightdesign.com

Service Bulletin

SB-ASTM-F2-02, Revision 02

Date of Initial Publication: 09-Sep-2024 Publication Date of this Revision: 26-Sep-2024

Step 3 Disassembling of Instrument console

3.1 Remove Displays GDU460 left and right, disconnect all connectors (See Pic.3.5)







Pic. 3.5 Monitor's GDU 460 Removing



Am Flugplatz 3, D-99820 Hörselberg Hainich, Airfield Eisenach-Kindel

Web: www.flightdesign.com; Phone: +49 36920 7530-10 E-mail: airworthiness@flightdesign.com

Service Bulletin

SB-ASTM-F2-02, Revision 02

Date of Initial Publication: 09-Sep-2024 Publication Date of this Revision: 26-Sep-2024

3.2 Remove other Garmin devices specified by the aircraft specification, disconnect all connectors (See pic.3.6)





Pic.3.6 Garmin devises removing

\wedge	LIFTAIR
FLIG	HT DESIGN

Am Flugplatz 3, D-99820 Hörselberg Hainich, Airfield Eisenach-Kindel

Web: www.flightdesign.com; Phone: +49 36920 7530-10 E-mail: airworthiness@flightdesign.com

Service Bulletin

SB-ASTM-F2-02, Revision 02


Date of Initial Publication: **09-Sep-2024**Publication Date of this Revision: **26-Sep-2024**

3.3 Remove circuit breakers from upper panel (See pic. 3.7)

• Note: Circuit breakers are part of wiring harnesses fuselage.







Pic. 3.7 Circuit breakers removing

^	LIFT AIR ⊙
FLIC	HT DESIGN

Am Flugplatz 3, D-99820 Hörselberg Hainich, Airfield Eisenach-Kindel

Web: www.flightdesign.com; Phone: +49 36920 7530-10 E-mail: airworthiness@flightdesign.com


Service Bulletin

SB-ASTM-F2-02, Revision 02

- 3.4 Unscrew 8 pcs screws AN526-1032R10 (See pic.3.8). Picture is describing left side, for right side is mirrored.
- 3.5 Dismount Hatch. Unscrew AN526-832R6 -5 pcs (See pic.3.8)
- 3.6 Dismount upper attachment points of instrument console. Unscrew Self-locking nuts M5 2pcs with washers DIN 9021. Location is shown on pic.3.9.1 and 3.9.2.
- Note: Lock nut M5 DIN 985 should be changed with a new one while assembling in part 3.
- **Note:** In older configuration of F2-LSA upper attachment points are differ (See Pic.3.9.3). To dismount upper attachment points of instrument console the 3 screws M4x12 DIN 7380 should be unscrewed.



Pic. 3.8 Dismounting of instrument console and fuel hatch



Pic. 3.9.1 Attachment points on Fuselage. Bonding Fastener M5




Am Flugplatz 3, D-99820 Hörselberg Hainich, Airfield Eisenach-Kindel

Web: www.flightdesign.com; Phone: +49 36920 7530-10


E-mail: airworthiness@flightdesign.com

Service Bulletin

SB-ASTM-F2-02, Revision 02



Pic. 3.9.2 Dismount upper attachment points of instrument console



Pic.3.9.3 Upper attachment points of Instrument console for previous configuration

^		LIFTAIR
*	FLIGHT	DESIGN

Am Flugplatz 3, D-99820 Hörselberg Hainich, Airfield Eisenach-Kindel

Web: www.flightdesign.com; Phone: +49 36920 7530-10 E-mail: airworthiness@flightdesign.com

Service Bulletin

SB-ASTM-F2-02, Revision 02

Date of Initial Publication: **09-Sep-2024**Publication Date of this Revision: **26-Sep-2024**

3.7. Remove instrument console from Fuselage. View of removed instument console is shown on pic.3.10

Note: All connectors should be disconnected.


Caution: Remove the instrument console carefully so as not to touch the handle of the rescue system.

Caution: Yellow wire of OVP module must be cutted during operation of removing. In part 3 of this SB this

connection must be restored (See pic.3.10.1)



Pic. 3.10 Removed instrument console



Pic. 3.11 Yellow wire of OVP module cutted



Am Flugplatz 3, D-99820 Hörselberg Hainich, Airfield Eisenach-Kindel

Web: www.flightdesign.com; Phone: +49 36920 7530-10 E-mail: airworthiness@flightdesign.com

Service Bulletin


SB-ASTM-F2-02, Revision 02

Date of Initial Publication: **09-Sep-2024**Publication Date of this Revision: **26-Sep-2024**

Part 2 Removing the Fuel selector valve and installing the new one with all needed additional parts

Step 1 Lower section panel adjusting

- 1.1 Produce slots in lower panel according to sketch (See pic.3.12) View B, C use tools from chapter 2.4.
- **Note:** In some older configurations of F2-LSA lower section panel is already fit with with the new design Fuel Selector Handle Cover (see table 1.) In this case, no step is needed.



Pic. 3.12 Lower section panel

^	LIFTAIR
FLIGH	IT DESIGN

Am Flugplatz 3, D-99820 Hörselberg Hainich, Airfield Eisenach-Kindel

Web: www.flightdesign.com; Phone: +49 36920 7530-10 E-mail: airworthiness@flightdesign.com

Service Bulletin

SB-ASTM-F2-02, Revision 02

Date of Initial Publication: 09-Sep-2024 Publication Date of this Revision: 26-Sep-2024

Step 2 Adjusting of Fuel selector mounting plate

- 2.1 Adjust Fuel selector mounting plate
- 2.1.1 Install mounting plate to the vise with aluminium inserts (See pic.3.12.2)
- 2.1.2 Set dimension hole position for stopper (See pic. 3.12.1). It should be between 9 and 6 o'clock position.
- 2.1.3 Drill hole 2,5mm to a depth of approximately 5mm. The bolt head must be flush with the plane (See pic. 3.12.1)
- 2.1.4 Cut the M3 thread, install bolt M3x8-8.8 (See table 1 pos. 24)

Note: Use Bonding liquid middle strength (Green) for installation bolt (See chapter 2.3.3).

- 2.1.5 Cut partly attachment point as described on pic. 3.12.1
- Use tools for metall parts adjusting See chapter 2.4



Pic.3.12.1 Adjusting of Fuel selector mounting plate



Pic.3.12.2 Process of Mounting plate adjusting



Am Flugplatz 3, D-99820 Hörselberg Hainich, Airfield Eisenach-Kindel

Web: www.flightdesign.com; Phone: +49 36920 7530-10 E-mail: airworthiness@flightdesign.com

Service Bulletin

SB-ASTM-F2-02, Revision 02

Date of Initial Publication: **09-Sep-2024**Publication Date of this Revision: **26-Sep-2024**

Step 3 Assembling Fuel selector handle cover, Mounting plate, Selector handle with lower section panel


3.1 Install adjusted Mounting plate, new design Fuel Selector Handle Cover (See table 1 pos.10) to lower section panel (See Pic.3.13).

Note: Position of mounting plate should correcspond with Pic.3.13.

Note: Use washers DIN 125 5,3 which were dismounted on step 2.6, Use Washer DIN 9021-5,3mm (See table 1

pos.28).

Note: Use Bolts M5x20 (See table 1 pos.22).



Pic.3.13 Installation of Mounting plate with new design Fuel Selector Handle Cover

^	LIFT AIR ⊙
FLIC	HT DESIGN

Am Flugplatz 3, D-99820 Hörselberg Hainich, Airfield Eisenach-Kindel

Web: www.flightdesign.com; Phone: +49 36920 7530-10

E-mail: airworthiness@flightdesign.com


Service Bulletin

SB-ASTM-F2-02, Revision 02


Date of Initial Publication: 09-Sep-2024 Publication Date of this Revision: 26-Sep-2024

Step 4 Removing the Fuel selector valve and installing the new one

- Disassemble Supply and Return fuel lines of left and right Fuel tank. Dismount Fitting AN816-6D-4pcs, Sleeve AN819-6D - 4pcs, Coupling nut AN818-6D-4pcs (See Pic.3.15).
- 4.2 Disassemble Supply and Return fuel lines in lower area of selector valve. Dismount Fitting AN816-6D-2pcs, Fitting 90 deg 3/8" - 2 pcs (See Pic.3.15).
- 4.3 Unscrew Bolts M4x8 with Lock washers – 3pcs (See Pic.3.15)
- Remove the Fuel selector valve with Fuel bracket (Pic.3.15 view W). 4.4
- 4.5 Unscrew screw MS24694C49-1pcs (See Pic.3.16).
- Unscrew screw MS51959-43 4pcs (See Pic.3.15). 4.6
- Remove Selector plate (pos.5,51) and switches (pos.46,49,11) 4.7
- Note: Positions 3,4,5,14,35,39,50,53,80 on pic. 3.16 and pos.43,61,64 on pic. 3.15 will not be used.
- Note: Pin pos.37 on pic. 3.16 will be used.
- Remove fuel aluminium tubes with fittings, clamps and short fuel hoses (See pic.3.16.1). 4.8
- Note: Parts removed on step 4.8 will not be used.



Pic. 3.15 Removing the Fuel selector valve



Pic. 3.16 Removing the Fuel selector valve




Am Flugplatz 3, D-99820 Hörselberg Hainich, Airfield Eisenach-Kindel

Web: www.flightdesign.com; Phone: +49 36920 7530-10 E-mail: airworthiness@flightdesign.com

Service Bulletin

SB-ASTM-F2-02, Revision 02



Pic. 3.16.1 Removing of Fuel lines from Fuel tanks




Am Flugplatz 3, D-99820 Hörselberg Hainich, Airfield Eisenach-Kindel

Web: www.flightdesign.com; Phone: +49 36920 7530-10 E-mail: airworthiness@flightdesign.com

Service Bulletin

SB-ASTM-F2-02, Revision 02

- 4.9 Produce preassembly of new Fuel selector duplex valve (See table 1 Pos.1).
- **Note:** All connections of fuel lines with fittings grease surfaces should sealed with EZ TURN (FUELLUBE) 5 OZ TUBE (see chapter 2.3.1).
- 4.9.1 Install Fittings to Fuel selector valve with preassure relief line (See pic.3.17)
- Note: All fittings and parts needed for assembly are indicated in table 1.





- 1- FS2020 Duplex Fuel Selector -1pcs
- 2- Check Valve CK375-MH-14-BRP -1pcs
- 3- T flared tube AN6 Male-female -1pcs
- 4- AN824-6D TEE 3/8 OD, 9/16"-18 -1pcs
- 5- Phenix Swivel Coupler Stright AN6-AN6 fitting -1pcs
- 6- PHENIX 90 deg Hose end 3/8" AN6 J3690-2 -4pcs
- 7- PHENIX 90 deg Swivel Coupler AN6-AN6 Fitting C690-2-1pcs
- 10- Swage fitting 10mm Nut 9/16-18 UNF -1pcs
- 15- Smooth I.D. Clamps JS2429 -4pcs
- 16- Fuel pipe, vehicle FUELPIP-3E-(FPMECO)-BLACK-D9,3X15,3-0,3m
- 17- Fire sleave- 0,3m

Pic. 3.17 Preassembly of Fuel selector valve



Am Flugplatz 3, D-99820 Hörselberg Hainich, Airfield Eisenach-Kindel

Web: www.flightdesign.com; Phone: +49 36920 7530-10

E-mail: airworthiness@flightdesign.com


Service Bulletin

SB-ASTM-F2-02, Revision 02

Date of Initial Publication: 09-Sep-2024 Publication Date of this Revision: 26-Sep-2024

Drill 4pcs extra holes Ø5mm and adjust central hole (See pic.3.17.1)





Pic. 3.17.1 Adjusting of Fuel bracket

4.9.3 Install preassembled new Fuel selector duplex valve (step 4.9.1) to Fuel bracket using bolts Screw ISO 7380 M5x20 (See



Am Flugplatz 3, D-99820 Hörselberg Hainich, Airfield Eisenach-Kindel

Web: www.flightdesign.com; Phone: +49 36920 7530-10 E-mail: airworthiness@flightdesign.com


Service Bulletin

SB-ASTM-F2-02, Revision 02

Date of Initial Publication: 09-Sep-2024 Publication Date of this Revision: 26-Sep-2024

table 1. Pos.22) and nuts M5 DIN 985 (See table 1. Pos.22) with new Selector plate (See table 1. Pos.14) and switches (pos.46,49,11 Pic.3.16)

- Note: Location of fitting parts are displayed on Pic. 3.17.2.
- Note: Use Loctite 648 for mounting bolts without self locking nuts.
- Note: Distance between Selector plate and Fuel bracket should be 3mm (See pic.3.17.3).



Pic. 3.17.2 Installation on Fuel Bracket



Pic. 3.17.3 Distance between Selector plate and Fuel bracket

4.9.4 Adjusting Connection flange ECA1#2 (See table 1 pos.14).

^		LIFTAIR
>	FLIGHT	DESIGN

Am Flugplatz 3, D-99820 Hörselberg Hainich, Airfield Eisenach-Kindel

Web: www.flightdesign.com; Phone: +49 36920 7530-10 E-mail: airworthiness@flightdesign.com

Service Bulletin

SB-ASTM-F2-02, Revision 02

Date of Initial Publication: **09-Sep-2024**Publication Date of this Revision: **26-Sep-2024**

4.9.4.1 Drill hole Ø3,5mm in Connection flange ECA1#2

4.9.4.2 Cut the thread 8-32


4.9.4.3 Install screw AN526-832R8-1pcs (See table 1 pos.25)

- Note: Use dimesions dirrectly from pic.3.17.2. The screw must point upward in relation to the three mounting points.
- **Note:** The screw installation length should correcspond with pic. 3.17.4.
- Note: Use Bonding liquid middle strength (Green) (See chapter 2.3.3).


4.9.4.4 Fix the Adjusted Connection flange ECA1#2 with Fuel selector valve using Screw M4x16 (See table 1 pos.29) Pic 3.17.5.

Note: Use Loctite 648 for mounting Screw M4x16.





Pic. 3.17.4 Adjusting Connection flange ECA1#2



Pic. 3.17.5 Fixing the Adjusted Connection flange ECA1#2 with Fuel selector valve

4.10 Install preassembled new Fuel selector valve back to Tunnel (See pic.3.18).




Am Flugplatz 3, D-99820 Hörselberg Hainich, Airfield Eisenach-Kindel

Web: www.flightdesign.com; Phone: +49 36920 7530-10 E-mail: airworthiness@flightdesign.com

Service Bulletin

SB-ASTM-F2-02, Revision 02

- 4.10.1 Screw the Screws ISO 7380 M5x35– 4pcs (See table 1 pos.23) with Nuts M5 and washers DIN 9021-5,3mm (See Pic.3.18).
- Note: Use Spacer for installation (See table 1 pos.11).



Pic.3.18. Installation of preassembled Fuel selector valve back to Tunnel



Am Flugplatz 3, D-99820 Hörselberg Hainich, Airfield Eisenach-Kindel


Web: www.flightdesign.com; Phone: +49 36920 7530-10 E-mail: airworthiness@flightdesign.com

Service Bulletin

SB-ASTM-F2-02, Revision 02

Date of Initial Publication: **09-Sep-2024**Publication Date of this Revision: **26-Sep-2024**

• **Note:** All connections of fuel lines with fittings grease surfaces should sealed with EZ TURN (FUELLUBE) 5 OZ TUBE (see chapter 2.3.1).



Pic.3.19 Connection the Return fuel line from upper side of Fuel selector valve

- 4.12 Connect the Engine Supply fuel line from upper side of Fuel selector valve
- 4.12.1 Assembly fittings with Fuel selector valve and Engine supply fuel line (See pic. 3.20 and 3.21)

Fitting 90 deg AN6-AN6-1pcs (See table 1 pos.7)

AN Fitting elbow AN821-6D-1pcs (See table 1 pos.8)

Straight AN6-AN6 Fitting -1pcs (See table 1 pos.5)

AN Fitting AN815-6D UNION - 1pcs (See table 1 pos.9)

• **Note:** All connections of fuel lines with fittings grease surfaces should sealed with EZ TURN (FUELLUBE) 5 OZ TUBE (see chapter 2.3.1).



Am Flugplatz 3, D-99820 Hörselberg Hainich, Airfield Eisenach-Kindel

Web: www.flightdesign.com; Phone: +49 36920 7530-10

E-mail: airworthiness@flightdesign.com

Service Bulletin

SB-ASTM-F2-02, Revision 02



Pic. 3.20 Connect the Engine Supply fuel line upper side view



Pic. 3.21 Connect the Engine Supply fuel line left side view

^		LIFTAIR
*	FLIGHT	DESIGN


Am Flugplatz 3, D-99820 Hörselberg Hainich, Airfield Eisenach-Kindel

Web: www.flightdesign.com; Phone: +49 36920 7530-10 E-mail: airworthiness@flightdesign.com


Service Bulletin

SB-ASTM-F2-02, Revision 02

- 4.13 Adjusting and installation of Return and Supply fuel lines from left and right Fuel tank.
- **Note:** All connections of fuel lines with fittings grease surfaces should sealed with EZ TURN (FUELLUBE) 5 OZ TUBE (see chapter 2.3.1).
- 4.13.1 Produce Fuel hoses 4pcs (See table 1. Pos.16) of Return and Supply fuel lines from left and right Fuel tank. Adjust needed length for connection with Fuel selector valve.
- 4.13.2 Produce Fire sleaves- 4pcs (See table 1. Pos.17) with length adjusted for Fuel hoses produced on step 4.12.1.
- 4.13.3 Connect Fuel hoses and Fire sleaves with aluminium tubes from AB-pillar (See pic.3.22,3.23). Use Smooth I.D. Clamps JS2429-4pcs (pos.15 table 1) for installation Fuel hoses and Clamp ABA 9W 15-24/9 S20-4pcs (pos.18 table 1) for installation Fire sleaves.
- **Note:** On the ends of fire sleave Odurless End Dip should be applied (See chapter 2.3.4). From every side 20mm (inner surface).
- 4.13.4 Connect Fuel hoses with Fire sleaves directly on Fuel selector valve's fittings (See pic.3.24). For connection Fuel hoses and Fire sleaves use clamps Smooth I.D. Clamps JS2429-8pcs.
- **Note:** On the ends of fire sleave Odurless End Dip should be applied (See chapter 2.3.4). From every side 20mm (inner surface).



Pic. 3.22 Installation of Fuel hose with Smooth clamp



Pic.3.23 Installation of Fire sleaves



Am Flugplatz 3, D-99820 Hörselberg Hainich, Airfield Eisenach-Kindel

Web: www.flightdesign.com; Phone: +49 36920 7530-10

E-mail: airworthiness@flightdesign.com

Service Bulletin


SB-ASTM-F2-02, Revision 02

Date of Initial Publication: 09-Sep-2024 Publication Date of this Revision: 26-Sep-2024



Pic. 3.24 Connecting Fuel hoses with Fire sleaves directly on Fuel selector valve's fittings

4.13.5 Fixation of Fuel hoses and Fire sleaves to Fuselage. Use Pipe and Fastening clamp 20mm DIN 3016 - 4pcs (See table 1 pos.19) and nut M5 DIN 985 (See table 1 pos.20) for fixation Fuel hoses with Fire sleaves on Frame 1 (Pic.3.25). For left and right side of fuselage is similar.



Pic.3.25 Fixation of Fuel hoses and Fire sleaves to Fuselage

Step 5 Leak test system pressure 0.2...0.25 bar. at wing fuel lines disconnected from fuel tanks intakes.



Am Flugplatz 3, D-99820 Hörselberg Hainich, Airfield Eisenach-Kindel

Web: www.flightdesign.com; Phone: +49 36920 7530-10 E-mail: airworthiness@flightdesign.com

Flight Design general aviation GmbH

Service Bulletin

SB-ASTM-F2-02, Revision 02


Date of Initial Publication: 09-Sep-2024 Publication Date of this Revision: 26-Sep-2024

Step 6 Connector's pin-out correction

Change wires on Faston connector according new Fuel selector valve's positions.

Open the connector, Swap the Black and Yellow wires, assembly connector.

The initial arrangement of wires in the connector is shown on Fig.3.26.



Pic.3.26 The initial arrangement of wires in the Faston connector

Part 3 Assembly of previously disassembled parts and settings

Note: Assembly diagrams are described in detail in the graphic materials of Part 1 of the SB.

Step 1 Installation of instrument console back to Fuselage

- 1.1 Install instrument console back to Fuselage.
- 1.1 Restore connection of Yellow wire of OVP (See pic.3.10.1).
- Caution: Connection of Yellow wire of OVP module which was cutted on step 3.7 must be restored (See pic.3.10.1).
- Note: Use crimping tool from chapter 2.4.4, use Socket isol. (See table 1 Pos.15)
- 1.3 Connect all connectors disassembled on step 3.7.
- 1.4 Screw 8 pcs screws AN526-1032R10 (See pic.3.8). Picture is describing left side, for right side is mirrored.
- 1.5 Install Hatch. Screw AN526-832R6 -5 pcs (See pic.3.8).
- 1.6 Assemble upper attachment points of instrument console. Screw Self-locking nuts M5 2pcs with washers DIN 9021. Location is shown on pic.3.9.1 and 3.9.2.
- Lock nut M5 DIN 985 should be changed with a new one while assembling.
- In older configuration of F2-LSA upper attachment points are differ (See Pic.3.9.3). To mount upper attachment points of instrument console the 3 screws M4x12 DIN 7380 should be Screwed.

^	LIFT AIR ⊙
FLIC	HT DESIGN

Am Flugplatz 3, D-99820 Hörselberg Hainich, Airfield Eisenach-Kindel

Web: www.flightdesign.com; Phone: +49 36920 7530-10 E-mail: airworthiness@flightdesign.com **Service Bulletin**


SB-ASTM-F2-02, Revision 02

Date of Initial Publication: **09-Sep-2024**Publication Date of this Revision: **26-Sep-2024**

- 1.7 Install Circuit breakers on upper panel (See pic. 3.7).
- 1.8 Install Garmin devices specified by the aircraft specification, connect all connectors (See pic.3.6).
- 1.9 Install Displays GDU460 left and right, connect all connectors (See Pic.3.5).

Step 2 Installation of Lower section panel

2.1 Connect Fuel selector extension from side of selector valve directly to Connection flange ECA1#2 using pin removed on step 4.7 (pos.36 Pic.3.16). Scheme of installation is on pic.3.27



Pic.3.27 Fuel selector extension installation

- 2.2 Connect electric connections of devices installed on Lower section panel.
- 2.2 Assemble Heat Grip. Screw Knurled nut (See pic.3.4).
- 2.3 Screw 4 pcs screws AN526-832R8 with polyamide washers (See pic.3.4).
- 2.2 Install Fuel selector handle. Screw 1 pcs screw M3x15 (See Pic.3.28).



Pic. 3.28 Fuel selector handle intallation

^	LIFT AIR O
FLIGHT	DESIGN

Am Flugplatz 3, D-99820 Hörselberg Hainich, Airfield Eisenach-Kindel

Web: www.flightdesign.com; Phone: +49 36920 7530-10

E-mail: airworthiness@flightdesign.com

Service Bulletin

SB-ASTM-F2-02, Revision 02

Date of Initial Publication: 09-Sep-2024 Publication Date of this Revision: 26-Sep-2024

Step 3 Installation of Armrest

- 3.1 Install armrest on the Tunnel and Connect the Jack connectors (See Pic.3.3).
- 3.2 Assemble the throttle grip (See Pic.3.2).
- Note: Lock nut M3 DIN 985 should be changed with a new one while assembling throttle grip.
- 3.3 Screw bolts AN526-832R6 -6pcs and Knob ball 1pcs (See Pic.3.1).
- Note: Use Loctite 648 for the Knob ball.

Step 4 Fuel tank timer settings

Setup of Fuel Tank reminder:

A reminder for switching fuel tanks. The reminder message repeats at the specified interval after the beginning of each trip.

Changing Alarm settings (PFD Normal operational mode):

- 1) Press the MENU key twice to display the Main Menu (See Pic.3.29);
- 2) Tap 'Setup' (See Pic.3.29);
- 3) Tap 'Alarms' (See Pic.3.30);
- 4) In area of 'Fuel Tank Reminder':
- 4.1) Tap on right dropdown content menu and chose 'Time';
- 4.2) Set time in left arrowkey's menu to '30:00'
- 5) Press the BACK key once to came back to Setup menu

Changing Sound settings (PFD Normal operational mode):

- 6) Tap 'Sound';
- 7) Scroll down to 'Message Tone' menu:
- 7.1) Tap on dropdown content menu and chose 'Enabled' (See Pic.3.32);
- 7.2) Set Message Tone Volume in left arrowkey's menu to '60%' (See Pic.3.33);
- 8. Press the BACK key three times to came back to Normal operational mode.



Pic.3.29 Main menu



Am Flugplatz 3, D-99820 Hörselberg Hainich, Airfield Eisenach-Kindel

Web: www.flightdesign.com; Phone: +49 36920 7530-10

E-mail: airworthiness@flightdesign.com

Service Bulletin

SB-ASTM-F2-02, Revision 02



Pic.3.30 Setup menu



Pic.3.31 Alarms Setup



Am Flugplatz 3, D-99820 Hörselberg Hainich, Airfield Eisenach-Kindel

Web: www.flightdesign.com; Phone: +49 36920 7530-10

E-mail: airworthiness@flightdesign.com

Service Bulletin

SB-ASTM-F2-02, Revision 02



Pic.3.32 Sound Setup



Pic.3.33 Message Tone Volume

FLIGHT DESIGN	
Flight Design general aviation GmbH	Q.D.

Tight Design general aviation GmbH
Am Flugplatz 3, D-99820 Hörselberg Hainich,

SB-ASTM-F2-02, Revision 02

Airfield Eisenach-Kindel
Web: www.flightdesign.com; Phone: +49 36920 7530-10
E-mail: airworthiness@flightdesign.com

Service Bulletin

Date of Initial Publication: **09-Sep-2024**Publication Date of this Revision: **26-Sep-2024**

3.4 Documentation

Conduct of this SB must be logged in the aircraft log book with date and signature of the responsible Person conducting the SB. National regulations have to be considered.

4 Appendix

4.1 Changes to Previous Revision

4.1.1 Chapter 3.3 Part 3 Step 4 Fuel tank timer settings updated. Steps changed. Pictures added.

4.2 Feedback Template

Use the subsequent feedback template to report completion to Flight Design.

If this SB was completed in accordance with the previous revision and the feedback template was completed, then filling out a new feedback template is not required.

^		LIFTAIR
>	FLIGHT	DESIGN

Am Flugplatz 3, D-99820 Hörselberg Hainich, Airfield Eisenach-Kindel

Information to obtain spare parts

Web: www.flightdesign.com; Phone: +49 36920 7530-10 E-mail: airworthiness@flightdesign.com

Service Bulletin

SB-ASTM-F2-02, Revision 02

Date of Initial Publication: **09-Sep-2024**Publication Date of this Revision: **26-Sep-2024**

This form has to be used to coordinate with Flight Design the required spare parts and to communicate the completion of the SB listed in the header of this page.

Submission can be done by mail, Fax or as scanned copy by e-mail to Flight Design GmbH (see header of this page) or to your national Flight Design Distributor who will forward the information for you.

Aircraft Type:	F2		
Model:	F2-LSA		
Serial Number: Aircraft Owner, Name and Address:			
Fuel selector valve has been replaced	Yes No No		
Fuel tank reminder has been set	Yes No No		
Confirmation of Completion Conduct of this SB has been done at the following workshop:			
Responsible Mechanic:			
Date: Location:	Signature:		

▲ Warning: As long as the form has not been submitted to Flight Design, this SB is considered not complied with for the respective aircraft.

Note: If this SB was completed in accordance with the previous revision and the feedback template
was completed, then filling out a new feedback template is not required.