

Service Bulletins					
Download	Date	Subject	Affected	Compliance	Manual
SB- SECS –CT Supralight-99	03-02-2021	Equipment Manufacturer Notification	n/a	n/a	at each annual inspection
SB- SECS –CT Supralight-02	02-10-2015	Verification of Rescue System Cover Installation.	up to s/n E-14-02-03 (including)	latest within 3 months following the issue date of this Notification, or at the next annual inspection of the aircraft, whichever comes first.	n/a
SB- SECS –CT Supralight-03	02-10-2015	Inspection Horizontal Tail.	Aircraft S/N that have a horizontal tail produced of Aramid fabric installed	with each 100 hrs inspection	n/a