

Safety Alerts					
Download	Date	Subject	Affected	Manual	Compliance
SA-ASTM-CTHL-03	04-11-2014	Installation verification of BRS Pickup Collar	All aircrafts with Airframe Emergency Parachute System BRS 1350 HS installed, and with S/N up to C-11-11-02, included. Aircraft with higher S/N are not affected.	prior to next flight	n/a
SA-ASTM-CTHL-02	07-03-2013	Inspection for applicability of Rotax ASB-912-062UL R1 / ASB-914-044UL R1, ASB-912-062R1 / ASB-914-044R1.	All CT and MC type aircrafts with aircraft serial number earlier than x 12 05 02 (excluded, with (x) being the identifier of the relevant model, when applicable), where in addition the engine has been exchanged on aircraft after delivery of the aircraft from the factory.	prior to next flight	n/a
SA-ASTM-CTHL-01	28-11-2011	Checking of the Crankshaft Journal for ROTAX Engine Type 912 and 914	All S/N up to S/N C-11-02-01 (inclusive)	before next flight, but at latest before 01 January 2012	n/a